Maryland Historical Trust

Maryland Inventory	y,of Historic Properties number:_	M:25-26
		HOUSE PROVOULA AMS PR

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

M Eligibility Recommended			MARYLAND HISTORICAL TRUST Eligibility Not Recommended X		
Criteria:A	B	c _	D Considerations: A B C D E F G None		
Comments:		· · · · · · · · · · · · · · · · · · ·			
Reviewer, OPS:_Anne E. Bruder Date:3 April 2001			Date:3 April 2001		
Reviewer, NR Program:Peter E. Kurtze			Kurtze Date:3 April 2001		

Sul

NAME AND SHA NO.: M- 021

LOCATION Road Name and Number: Piney Meetinghouse Road over Watts Branch City/Town: Rockville X vicinity Montgomery
Ownership: _ State X County _ Municipal _ Other
Bridge projects over: _ Road _ Railway X Water _ Land
Is bridge located within designated district?: _ yes _X no NR listed district _ NR determined eligible district locally designated _ other Name of District _
BRIDGE TYPE
Timber Bridge Beam Bridge Truss-Covered Trestle Timber-and-Concrete
Stone Arch Bridge
Metal Truss Bridge
Moveable Bridge Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder Rolled Girder Rolled Girder Concrete Encased Plate Girder Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
X Concrete Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name 585

DESCRIPTION

Describe the Setting:

Bridge M- 021 spans Watts Branch in southwest Montgomery County. Carrying Piney Meetinghouse Road in a generally north-south direction over the primarily southwestern flowing creek, the bridge stands within the Piedmont physiographic province of Maryland. Much of the surrounding land consists of rolling hills although recent suburban development has encroached within a few hundred yards of the bridge.

Describe the Superstructure and Substructure: (Discuss points identified in Context Addendum, Section C)

Bridge M- 021 consists of a single concrete-beam span totaling 49 feet in length. The bridge carries a clear roadway of 18 feet width topped by a macadam wearing surface. A concrete-pier and metal-pipe railing protected by w-beam guardrails flanks the roadway. The guardrails extend into the roadway approaches as well. Concrete abutments and wing walls support the bridge superstructure.

Recent inspections of the bridge have described its condition as fair. Repairs undertaken in 1991 utilized epoxy grout to fill spalled sections of the concrete structure. Most beams feature longitudinal cracks with heavy efflorescence and rust staining. Vertical cracks on the abutments extend the entire length of the abutment face and end after entering the waterline.

A survey of historic concrete beam bridges undertaken by the Maryland State Highway Administration in the Fall of 1995 identified 113 bridges of that type located throughout the state. Slightly more than two-thirds (76) of that total were single-span bridges.

Discuss major alterations:

County inspection records do not describe any major alterations undertaken on Bridge M-0021.

HISTORY

When Built: circa 1950 (Maryland Historical Trust documents)

Why Built: Unknown
Who Built: Unknown
Who Designed: Unknown
Why Altered: Not applicable.

Was this bridge built as part of an organized bridge building campaign?: Research has not identified any organized building campaigns associated with Bridge M-0021's construction.

SURVEYOR ANALYSIS

This bridge may have NR significance for association with:

_ A (Events) _ B (Person) _ C (Engineering/Architectural Character)

Was this bridge constructed in response to significant events in Maryland or local history?

Research has not revealed any associations between the bridge's construction and significant events contributing to Maryland and/or local history.

When the bridge was built, and/or given a major alteration, did it have a significant impact on the growth and development of the area?

Construction of Bridge M-0021 does not appear to have had any significant impact on local development or growth.

Is the bridge located in an area which may be eligible for historic designation, and would the bridge add or detract from the historic and visual character of the possible district?

No, Bridge M-0021 is not located in an area potentially eligible for historic designation.

Is the bridge a significant example of its type?

No, this bridge is not a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Bridge M- 021 appears to retain fair integrity of its character defining elements.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer, and why?

County records do not identify the original construction authority, and therefore evaluating the bridge as a significant example of its manufacturer is problematic.

Should this bridge be given further study before significance analysis is made, and why?

Yes. Further study may identify the original construction body.

BIBLIOGRAPHY

Freese, Jo Ellen

1995

Correspondence with Stewart B. Taub, Wallace Montgomery & Associates, Towson, MD. From Maryland Historical Trust, 29 December 1995. Copy on file at Maryland State Highway Administration, 707 North Calvert Street, Baltimore, MD.

Montgomery County Department of Transportation

Bridge Inspection Reports. On file at 101 Monroe Street, Rockville, MD.

Spero, P.A.C., & Company, and Louis Berger & Associates, Inc.

1994

Historic Bridges in Maryland: Historic Context Report. Maryland State Highway Administration, Baltimore.

State Roads Commission of Maryland

1958

A History of Road Building in Maryland. Baltimore.

SURVEYOR INFORMATION

Name:

Stuart Paul Dixon


Organization:

KCI Technologies, Inc.

Address:

5001 Louise Dr., Suite 201 Mechanicsburg, PA 17055 Date: 13 May 1996

Telephone: <u>(717)</u> 691-1340





Inventory #<u>M: 25-26</u>

Name M21-PINEY MEETING HOUSE OVER WATTS BRANCH
County/State MONTGOMERY / MP
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description SOUTH APPRDACH
Number K of 36 4

10 a k



Inventory # M: 25-26

Name M21-PINEY MEETING HOWE OVER WATTS BRANC
County/State MONTGOMERY MO
Name of Photographer FRANK JULIANO
Date 2/95
·
Location of Negative SAR
Description ELEVATION LOOKING EAST
•
Number 5 of 26



Inventory # M: 25-26

Name M21 - A NEY MEETING HOWE OVER WATTS BRANCH
County/State MONTOOMERY MO
Name of Photographer FRANK JULIANO
Date 7 95
Location of Negative SHR
Description MORTH APPROACH
Number of Sta
Number of



Inventory #<u>M</u>: 25-26

Name M21 - PINEY MEETINGHOUSE OVER WATTS BRANCH
County/State Monroomery mo
Name of Photographer FRANK JULIANO
Date
Location of Negative SHA
Description ExEVATION LOOKING WEST
1
4
Number <u>of </u>